
| CITY OF BALTIMORE WET W SMOKE AND DYED W | Page _/_ of <u>~3</u> | |
|---|--------------------------------------|--|
| Sewershed: PATAPSCO | Company: Savin Engineers | Date: <u>9-/5-09</u> |
| Test to be Performed: Smoke: X Dyed Water: | Ground Condition: Dry: X Damp: Wet: | Supervisor: Joe Mirabito |
| Manhole ID: <u>S49wl,oo2 m u</u> | Test ID: <u>\$/04/-020</u> | Notifications Made: ½ (Residents, Fire, 311) |

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



| OLTA OF DALTIMODE METANEATHER COMORNE RECORDS | | | | | | | | | | |
|---|-------------------|-------------------------|--------------------|---------------|-------------------|-----------------------|------------------------|----------------|--------------|--|
| CITY OF BALTIMORE WET WEATHER CONSENT DECREE Page 2 of 3 | | | | | | | | | of 3 | |
| SMOKE AND DYED WA | | | | ATER T | STING | FORM | ·g · | | | |
| Sewer | shed: PATAP | SCO | | Compan | y: <u>SAV</u> | TN | | Date: 9/15 | 6/09 | |
| | | | | • | | | | | | |
| Test to | be Performed: | | | | Condition | | | Supervisor:JAM | | |
| Smoke | e: <u>X</u> Dy | ed Water: | | Dry: <u>X</u> | Dry: X Damp: Wet: | | | | | |
| | | | | | | Notifications Made: X | | | | |
| Manhole ID: <u>S49W1_002MH</u> | | | Test ID: S1041-020 | | | | (Residents, Fire, 311) | | | |
| | | | | | | | | | | |
| Field Sketch: (Show all Manholes with Numbers, Blower Placement Location, Sandbag or Isolation | | | | | | | | | | |
| Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers) | | | | | | | | | | |
| Defect | | | | Source | | | Drainage | | Photo | |
| No. | | Address | | Туре | Location | | Area | Severity | Number | |
| | 3230 SUN ST | | | 3 | 7 | 2 | 25 | 3 | P01 | |
| 2 | 3230 SUN ST | | | 3 | 7 | 2 | 25 | 3 | P01 | |
| | | | | | | | | | | |
| | | | | - | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | OBSER\ | ATION | CODES | | | | |
| | Source Type | Location | Sector | Severity | | Source Type | Location | | | |
| | Main Sewer | Paved Concrete | Public | No Smoke | | MH Frame Seal | Non-Paved | | | |
| | Service Line | Paved Asphalt | Private | Trace | | Storm Drain | Field/Woods | | | |
| | Cleanout | Paved Other | | Moderate | | Catch Basin/Inlet | , | | | |
| | Downspout | Driveway | | Major | | Storm Manhole | Golf Course | | | |
| | Area Drain | Sidewalk | | | | Storm Ditch | Other | | | |
| | Driveway Drain | Curb | | | | Excavation | | | | |
| | Stairwell Drain | Yard- Front | | | 16 | Other | | | | |
| | Foundation Drain | Yard-Back Yard- Side | | - | | | | | | |
| U9 | Building Interior | ı aru- Side | | 1 | Ī | | | 1 | i | |

| CITY OF BALTIMORE WET W SMOKE AND DYED W | Page <u>3</u> of <u>3</u> | |
|---|---------------------------|-----------------------------|
| Sewershed: PATAPSCO | Company: Savin Engineers | Date: 9/15/09 |
| Test to be Performed: | Ground Condition: | Supervisor: Joe Mirabito |
| Smoke: X Dyed Water: | Dry: X Damp: Wet: | |
| Manhole ID: S49W1 002MH | Test ID: S1041-020 | Notifications Made: X |

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



S1041-020-OB01-P01



S2041-020-OB02-P01